PAGE: 1

PRINT DATE: 10/26/95

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NONCRITICAL HARDWARE

NUMBER: M5-6MR-0027-X

SUBSYSTEM NAME: ORBITER DOCKING SYSTEM

REVISION:

SEP 30, 1995

PART NAME **VENDOR NAME**  PART NUMBER VENDOR NUMBER

LAU

: DOCKING SYSTEM POWER PANEL.

V828-730150

SRU

: FUSE

MC451-0018-0300

#### PART DATA

## EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

FUSE, PLUG-IN, SUB-MINIATURE, 3 AMP - PYRO LOGIC PWR MN A AND MN C CONTROL CIRCUIT.

REFERENCE DESIGNATORS: 36V73A7A3F1

36V73A7A3F2

QUANTITY OF LIKE ITEM: 2

(TWO)

# FUNCTION:

PROVIDE DISTRIBUTION AND CIRCUIT PROTECTION FOR THE MN A-ESS 1BC AND THE .. MNLC-ESS 3AB FROM THE RPCs ASSOCIATED WITH THE PECU PYRO LOGIC CIRCUITS.

- REFERENCE DOCUMENTS: 1) ECN 104-25012A, ODS ELECTRICAL CHANGE NOTICE.
  - 2) CKB>=468=31Z=001 \_ J"P. SCHEMATIC DIAGRAM -ANDROGYNOUS PERIPHERAL DOCKING SYSTEM (APDS)

CONTROL PANEL PU-APSS SCHEMATIC.

3) V828-733002. SCHEMATIC DIAGRAM - D&C PANEL A7A3.

AFT STATION

4) VS70-953104, ODS INTEGRATED SCHEMATIC.

5) 33Y.5212.005, "P. APDS CONTROL UNIT ELECTRICAL

SCHEMATIC.

6) 17RC±10> 2601F\_J "P. PYRO FIRING CONTROL UNIT

ELECTRICAL

PAGE: 2

PRINT DATE: 10/25/95

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NONCRITICAL FAILURE MODE NUMBER: M5-6MR-0022-01

REVISION# 1

SEP 30, 1995

SUBSYSTEM NAME: ORBITER DOCKING SYSTEM

LRU: MC451-0018-0300 ITEM NAME: FUSE

CRITICALITY OF THIS

FAILURE MODE: 193

FAILURE MODE:

FAILS OPEN

MISSION PHASE:

OO.

ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 104 ATLANTIS

CAUSE:

A) PIECE PART STRUCTURAL FAILURE, B) CONTAMINATION, C) VIBRATION, D) MECHANICAL SHOCK, E) PROCESSING ANOMALY, F) THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN

A) PASS

B) N/A

C) PASS

PASS/FAIL RATIONALE:

A)

B)

PYROTECHNIC SEPARATION CLASSIFIED AS STAND-BY REDUNDANCY.

METHOD OF FAULT DETECTION:

N/A

MASTER MEAS, LIST NUMBERS:

NONE

CORRECTING ACTION:

NONE

- FAILURE EFFECTS -

(A) SUBSYSTEM:

LOSS OF CAPABILITY TO ACTIVATE ONE OF THE TWO PECU LOGIC CIRCUITS.

(B) INTERFACING SUBSYSTEM(\$):

DEGRADED REDUNDANCY FOR PYROTECHNIC SEPARATION CAPABILITY. LOSS OF ONE OF TWO 4Y LOGIC SIGNALS TO THE PECU.

# FAILURE MODES EFFECTS ANALYSIS (FMEA) - NONCRITICAL FAILURE MODE NUMBER: M5-6MR-0022-01

- (C) MISSION: NO EFFECT.
- (D) CREW, VEHICLE, AND ELEMENT(S): FIRST FAILURE NO EFFECT.
- (E) FUNCTIONAL CRITICALITY EFFECTS:

  POSSIBLE LOSS OF CHEW OR VEHICLE AFTER FOURTHREE FAILURES. 1) FUSE OPENS. DEGRADED REDUNDANCY FOR PYROTECHNIC SEPARATION. 2) FUSE IN THE REDUNDANT CIRCUIT FAILS OPEN RESULTING IN LOSS OF PYRO ARMING CIRCUIT CAPABILITY AND THEREFORE LOSS OF PYROTECHNIC UNDOCKING CAPABILITY. LOSS OF PECU LOGIC. LOSS OF PYROTECHNIC UNDOCKING CAPABILITY. 3) ONE OF TWELVE HOOKS FAILS TO OPEN (REF. M8-1MR-BM001-04.) LOSS OF CAPABILITY TO IMPLEMENT NOMINAL SEPARATION. LOSS OF NOMINAL AND PYROTECHNIC SEPARATION CAPABILITY. PERFORM EVA TO REMOVE 96 BOLTS HOLDING DOCKING BASE TO EXTERNAL AIRLOCK. 4) FAILURE OF EVA TO REMOVE BOLTS. LOSS OF ALL UNDOCKING CAPABILITY.

### - TIME FRAME -

TIME FROM FAILURE TO CRITICAL EFFECT: DAYS

TIME FROM FAILURE OCCURRENCE TO DETECTION: MINUTES

TIME FROM DETECTION TO COMPLETED CORRECTIVE ACTION: MINUTES

TIME REQUIRED TO IMPLEMENT CORRECTIVE ACTION LESS THAN TIME TO EFFECT? YES

HAZARDS: DM2OHA04(F) ODS-18.

INABILITY TO SAFELY SEPARATE ORBITER FROM DOCKING MODULE OR MIR.

- APPROVALS -

PRODUCT ASSURANCE ENGINEERING PRODUCT ASSURANCE MANAGER

:R. BLACKWELL

:T. NGUYEN